


I n t e l l i N o t e s

Pin Identification for Connector J1 on the 7050-E



J1 Pin out - AES 7050-E.

The view of the plug is looking at the end of the connector as if it was on the end of a cable. The view of the jack is looking from above, down onto the printed circuit board.

- Pin 1 = GND, Ground
- Pin 2 = RX, Receive, Signal to 7050-E
- Pin 3 = TX, Transmit, Signal from 7050-E
- Pin 4 = DTR, Data Terminal Ready, Signal to 7050-E
- Pin 5 = DSR, Data Set Ready, Signal from 7050-E
- Pin 6 = +12 Volts DC